



$I_x = 8.17$
 $S_x = 3.34$

4\"/>




$I_x = 12.553$
 $S_x = 3.79$


\"/>



SIDE FASCIA



DRAIN BEAM FASCIA



END FASCIA

ALL ALUMINUM IS 6063-T6



Perfection Architectural Systems, Inc

Service, Quality, Reliability.

2310 Mercator Drive, Orlando, FL 32807
 407.671.6225 / 800.238.7207 Fax: 407.671.8252
www.perfectionarch.com

Gutters & Fascias